

HIMACHAL PRADESH
PUBLIC WORKS DEPARTMENT

No. PWI/CB/WA/Misc. Building/2025-26/ 8429-30
To

Dated: 01/02/26


✓ The Principal,
Partap World School
VPO. Chanour,
Indora-176401

Subject: - Renewal of School Building Safety Certificate for the year 2025-26.


Reference: - Your office Letter No. PWS/ 3545 dated 11.02.2026

The Building Safety Certificate in respect of Partap World School, VPO Chanour, Tehsil Indora (HP) for the year 2026-27 as requested vide letter quoted under reference is sent herewith.

DA/ Copy of Certificate.


Executive Engineer,
Indora Division, HP.PWD.
Indora.

Copy to the Assistant Engineer, Sub Division, HP.PWD. Badukhar for information w.r.t. his office Letter No. 922 dated 17.02.2026.


Executive Engineer,
Indora Division, HP.PWD.
Indora.


Manager
Partap World School
V.P.O..Chanour, Teh. Indora (H.P.)


Principal
Partap World School
VPO. Chanour Indora-176401

CERTIFICATE.

The inspection of School Building of Partap World School Indora, Tehsil Indora, Distt. Kangra (HP) situated on Khasra No. 137, 138, 139, 2345/141, 2347/141, 142, 2348/152, 2350/152, 2351/152, 153, 2352/154, 2354/154, 2355/154, 155, 156, 1577 and Khotuni No. 435 & 423 has been conducted by the Junior Engineer/ Assistant Engineer, Sub Division, HP. PWD. Badukhar. On the basis of their inspection report, it has been found that no Earthquakes resistant norms have been adopted for the construction of School building. No structural drawings approved by the competent Govt. agency were produced by the School authority. The structure of the building is a non-Engineering structure. Hence, the structural safety of building can't be ensured specially from Earthquake point of view. This Department will not responsible for any type of loss of life and property etc., if this structure fails under any circumstances.

However, as per visual inspection, the building appears to be safe and accordingly, the Building Safety Certificate is being issued by this Department from 01.04.2026 to 31.03.2027. This Department could not access the structural safety of said building as the same was not constructed under the supervision of this Department.

Place: -Indora.



Junior Engineer,
Sub Division, HP.PWD.
Badukhar.



Assistant Engineer,
Sub Division, HP.PWD.
Badukhar.



Executive Engineer,
Indora Division, HP.PWD.
Indora. 20/02/2026



Manager
Partap World School
V.P.O. Chanour, Teh. Indora (H.P.)



Principal
Partap World School
V.P.O. Chanour Indora-176401

Annexure D

BUILDING SAFETY CERTIFICATE

No. 8429-30

Dated: 21-02-2026

It is certified that the existing building PARTAP WORLD SCHOOL (name of the building or premises) at V.P.O. CHANOUR, TEH. INDORA, DIST. KANURA, (H.P.) 176401. (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1) A	Block (2) B	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	4	2				

The building is owned/occupied by PARTAP WORLD SCHOOL (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of H.P. PWD (Name of Department/ Govt.) on 17-02-2026 (date of inspection) in the presence of DR. VISHAL MAHAJAN, MANAGER OF P.W.D. (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 01-04-2026 for a period of 31-03-2027 years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 20-02-2026 at INDORA by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: 

Name: HARISH THAKUR

Designation: Asstt. Engineer

Name & Address of Department/ Office: H.P. PWD Badukhor.

**Assistant Engineer
Badukhor Sub Division,
Badukhar**


**Manager
Partap World School
V.P.O. Chanour, Teh. Indora (H.P.)**


**Principal
Partap World School
V.P.O. Chanour Indora-176401**